

**A.11.2 Caractérisation de jonctions de câbles MT vieillies en service**

LAMARRE Laurent, CHINH DANG - Hydro-Québec - Varennes - Canada

A.11.2 Characterization of medium voltage cable splices aged in service.

LAMARRE Laurent, CHINH DANG - Hydro-Québec - Varennes - Canada.

Résumé

Une étude portant sur l'état de jonctions de câble (moyenne tension) vieillies en service a été effectuée à Hydro-Québec. Les principaux modes de défaillance qui ont été identifiés sont: surchauffe du connecteur métallique entraînant dégradation rapide des isolants de la jonction; claquage aux interfaces du boîtier isolant. Une caractérisation plus poussée des divers matériaux du boîtier isolant a été effectuée pour tenter de mettre en évidence les principaux mécanismes de vieillissement.

Abstract

A study on service aged cable splices (medium voltage) has been performed at Hydro-Québec. The major failure modes which have been identified are: overheating of the metallic connector causing the insulating materials of the splice to degrade rapidly; breakdown at interfaces between insulating parts. A more thorough characterization of the various insulating materials was carried out in an attempt to identify the dominating aging mechanisms.